



3Com IntelliJack Switch NJ220 Release Notes

Software version 2.0.23

Part Number: 10016236 Rev. AA

Published Date: June 2007

Table of Contents

1. Introduction.....	2
1.1 Scope	2
1.2 Online Resources	3
1.3 Software License Agreement.....	3
2. Issues Fixed in IntelliJack NJ220 Release 2.0.23.....	3
3. Upgrading Software	4

1. Introduction

1.1 Scope

These release notes summarize the operational requirements and known issues for the following 3Com products.

Software Release Filenames	Description
nj220_020023.bin	3Com IntelliJack Switch NJ220 Model # 3CNJ220
	Note: The NJ220 software does not operate with any other 3Com switch.

1.2 Online Resources

To obtain a copy of the *3Com IntelliJack NJ220 User Guide*, visit the 3Com Web site:
www.3Com.com

To obtain the latest technical information for your Switch, including a list of known problems and solutions, visit the 3Com Knowledgebase:
<http://knowledgebase.3Com.com>

To obtain current software updates (maintenance releases) and associated release notes for the IntelliJack NJ220 and other 3Com products, visit the 3Com Web site:
www.3Com.com

1.3 Software License Agreement

Before you use the Switch software, please ensure that you read the license agreement text. You can find the `license.txt` file in the self-extracting exe that you have downloaded from the 3Com Web site.

2. Issues Fixed in IntelliJack NJ220 Release 2.0.23

The following issues have been resolved in this release of the NJ220 run-time software:

- **Problem setting VLAN ID**

Fixed an issue where the NJ220 would set a VLAN ID incorrectly after successful 802.1x authentication from a Radius server.

- **Problem with Broadcast Pings**

Fixed an issue where the NJ220 would respond to broadcast PING packets.

- **Problem moving to new network segment**

Fixed an issue where the NJ220 would use its previous IP address when it was moved to a new network segment.

- **Problem after Reboot**

Fixed an issue where the NJ220 would lose port settings when it was rebooted.

- **Problem communicating with Central Configuration Manager**

Fixed an issue where the NJ220 would restart when it received a loopback packet with a length field of zero. This would cause the NJ220 to stop sending event packets to the Central Configuration Manager utility.

3. Upgrading Software

To upgrade the NJ220 with the new versions of the Run-time image, use the IntelliJack Central Configuration Manager application.

For instructions on how to use the Central Configuration Manager, please refer to the *3Com IntelliJack NJ220 User Guide*.

CAUTION: Before upgrading the NJ220 Release 2.0.23 software, make sure that the Central Configuration Manager application is version 2.0.7 or higher. If an older version is used, the NJ220 may be able to be upgraded, however, after the upgrade is complete, the NJ220 will no longer be able to be discovered by the older Central Configuration Manger application.

To obtain the latest version of the IntelliJack Central Configuration Manager, visit the 3Com Web site: www.3Com.com