



RELEASE NOTE FOR THE **3C319 TOKENLINK VELOCITY ISA NETWORK INTERFACE CARD**

This release note describes the following network driver installation issues for the 3Com® 3C319 TokenLink® Velocity™ ISA network interface card (NIC):

- Novell NetWare server 4.1x installation options
- Novell NetWare server 3.12 installation options
- Novell NetWare Client 32 installation options
- TokenLink NDIS 4 driver incompatibility with some versions of Microsoft Windows

NetWare 4.1x Server Installations

When installing the 3C319 NIC in a NetWare 4.1x server, you can use either of the following drivers:

- 3CTOKEN.LAN driver and files from the \NW410 directory on *TokenDisk*® diskette #1
- 3C619B/3C619C driver supplied on the NetWare CD

NetWare 3.12 Server Installations

When installing the 3C319 NIC in a NetWare 3.12 server, you should use the 3CTOKEN.LAN driver and files from the \NW312 directory on *TokenDisk* diskette #2.

NetWare Client 32 Installations

When installing NetWare Client 32 for DOS/Windows, you can use either of the following drivers:

- 3CTOKEN.LAN driver and files from the \CLIENT32 directory on *TokenDisk* diskette #2
- 3C619B/3C619C driver supplied on the NetWare CD

Windows Incompatibility with NDIS 4 Driver

The NDIS 4 driver on *TokenDisk* diskette #2 is incompatible with the following operating systems:

- Retail version of Windows 95 (version 950)
- Windows NT 3.51

When installing the 3C319 NIC in a computer running either of these operating systems, load an NDIS 3 driver from the appropriate *TokenDisk* diskette #1 location shown in the following table:

Table 1 NDIS 3 Driver Locations on *TokenDisk* Diskette #1

Driver	Directory
Windows 95 NDIS 3	\\WIN95
Windows NT NDIS 3	\\WINNT

When installing the 3C319 NIC in a computer running Windows 95 OEM Service Release 2 (OSR2, or version 950b) or Windows NT 4.0, you can load an NDIS 4 driver from the appropriate *TokenDisk* diskette #2 location shown in the following table:

Table 1-1 NDIS 4 Driver Locations on *TokenDisk* Diskette #2

Driver	Directory
Windows 95 NDIS 4	\\ (root)
Windows NT NDIS 4	\\NT95

Copyright © 3Com Corporation, 1997. All rights reserved.

Unless otherwise indicated, 3Com registered trademarks are registered in the United States and may or may not be registered in other countries.

3Com, the 3Com logo, TokenDisk, and TokenLink are registered trademarks, and Velocity is a trademark of 3Com Corporation.

Other brand and product names may be registered trademarks or trademarks of their respective holders.